

Release Note LMWIN

◆ Release software

LMWIN

◆ Version number

Version 7.23

◆ Available schedule

October 14, 2016

◆ Target model

DT-900 series, DT-930 series, DT-X5 series, DT-X7 series, DT-10 series,
DT-11 series, IT-10 series, IT-500 series, IT-600 series, IT-800 series, IT-3000 series,
IT-3100 series, DT-X30 series, DT-X8 series, IT-300 series,
IT-9000 series, DT-970 series, IT-G500 series, DT-X100 series, DT-X200 series

◆ General

This communication software has been developed to transfer file between server and terminal.

◆ Changes from Version 7.18

- Fixed : Issue of error if DT-970 connects by 1 shot mode
- Fixed : Improve error log file output procedure on OS of Windows Vista or greater
- Fixed : (DT-970/IT-G500) Issue of transmission error handling that depends on the file size.
- Fixed : (DT-970) Issue of after removing the DT-970 from the cradle in the open state of 1SHOT mode, it can not communicate with the place the DT-970 in the cradle.
- Fixed : (DT-970) It is not able to communicate with multiple USB devices connected.
- Added : "Windows 8.1" in the manual of the operating environment.
- Added : "Windows 10" in the operating environment.

◆ Working environment

- Microsoft Windows 2000 Professional / Server (SP4 or a later version)
- Microsoft Windows XP Professional (SP2 or a later version)
- Microsoft Windows Server 2003 Standard (SP1 or a later version)
- Microsoft Windows Vista Business / Ultimate
- Microsoft Windows Server 2008 Standard (32bit) / R2 Standard (64bit)
- Microsoft Windows Server 2012 R2 (64bit)
- Microsoft Windows 7 Professional (32bit / 64bit)
- Microsoft Windows 8 Pro (32bit / 64bit)
- Microsoft Windows 8.1 (32bit / 64bit)
- Microsoft Windows 8.1 Pro (32bit / 64bit)
- Microsoft Windows Server 2012 R2 Standard (64bit)
- Microsoft Windows 10 Home (32bit / 64bit)
- Microsoft Windows 10 Pro (32bit / 64bit)
- Microsoft Windows 10 Enterprise (32bit / 64bit)

Note:

- For DT-900 series, Windows 2000 and Windows XP Professional support the LMWIN.
- The communication in B.S/B.B mode is not supported in Windows Server 2003 R2, Windows Server 2008, Windows Server 2012 and Windows 10.
- The communication with IT-10 in USB mode is not supported in Windows Server 2008 or later.
- The communication in USB(USB-SERIAL) mode is not supported in Windows 2000.
- In Windows 10 Home, LMWIN supports only DT-970.

◆ **How to check the software version**

Please confirm the software version in the Help and the About of the LMWIN. You will be able to find Version 7.23.

◆ **Caution**

Install procedure of IRXpress(USB and RS232C driver) for Windows 8.1 Pro (32bit) are different from regular installation process. Please refer install manual prior to install them.

◆ **How to get software**

Download from distributor support pages (Available from October 14, 2016)
Access following URL for download.

https://dealer.casio.jp/system_en/pa/PADealer/

Software Download

Every terminals

◆ **How to get the latest LMWIN manual**

Download from distributor support pages (Available from May 22, 2017)
Access following URL for download.

https://dealer.casio.jp/system_en/pa/PADealer/

Manuals

All the information in this bulletin is subject to change without prior notice to the distributors